



ELA AVIACIÓN, S.L.

Service Bulletin/Boletín de Servicio No. 10E-271025 (Rev 2)

Fuel leak in the pipes

Fuga de combustible en las tuberías

MANDATORY

OBLIGATORIO

Date of issue: November 25th, 2025

Fecha de publicación: 25 Noviembre 2025

1) Gyroplanes affected:
Autogiros afectados:

This Service Bulletin applies to the following gyroplane models equipped with Rotax 915 iS/Rotax 916 iS engines:

- ELA Eclipse EVO
- ELA Eclipse REVO

The affected aircraft requiring replacement of the fuel hose system are those manufactured between **20TH October 2021 and 4th January 2024** as well as all those that have requested the replacement as a spare part, with **serial numbers ranging from 651 to 711 (inclusive)**.

Operators are requested to verify their aircraft's serial number as indicated in the attached reference image to determine whether the aircraft is within the affected range.

From 651 to 711 inclusive / Desde el 651 al 711 ambos incluidos



El presente Boletín de Servicio aplica a los siguientes modelos de autogiro equipados con motores Rotax 915 iS/Rotax 916 iS:

- ELA Eclipse EVO
- ELA Eclipse REVO

Las aeronaves afectadas que requieren la sustitución del sistema de tubos de combustible son aquellas fabricadas entre **el 20 de octubre de 2021 y el 4 de enero de 2024**, así como todos aquellos que hayan solicitado el reemplazo como repuesto con **números de serie comprendidos entre el 651 y el 711 (ambos inclusive)**.

Se solicita a los operadores verificar el número de serie de su aeronave según se muestra en la imagen adjunta, con el fin de determinar si se encuentra dentro del rango afectado.



ELA AVIACIÓN, S.L.

Service Bulletin/Boletín de Servicio No. 10E-271025 (Rev 2)

Fuel leak in the pipes

Fuga de combustible en las tuberías

2) **Reason:**

Razón:

We have detected a fuel system leak in a few number of gyroplanes. Since this condition represents a potential safety hazard, the cessation of the flight operations has been mandated until the issue is resolved.

Hemos detectado una fuga en el sistema de combustible en un pequeño número de autogiros. Por este motivo, y considerando que esta condición representa un posible riesgo para la seguridad, hemos solicitado el cese de las operaciones de vuelo hasta que el problema haya sido corregido.

3) **Subject:**

Asunto:

Complete and mandatory replacement of the fuel system of the affected gyroplanes as indicated in this document.

Sustitución completa y obligatoria del sistema de combustible de los autogiros afectados indicados en este documento.

4) **Required actions:**

Acciones requeridas:

Do not operate/fly the affected gyroplanes until the fuel system replacement has been completed as specified in this Service Bulletin.

To proceed with the replacement, please contact the factory to order the **Ref.10E188** the new system and arrange the return of the defective components as soon as possible.

No volar los autogiros afectados indicados hasta no haber realizado la sustitución del sistema de combustible según se indica en este boletín.

Para proceder con la sustitución, póngase en contacto con la fábrica para solicitar la **Ref.10E188** del nuevo sistema y coordinar la devolución de los componentes defectuosos lo antes posible.

Contact us in technical.support@elaaviacion.com

Contacte con nosotros en technical.support@elaaviacion.com

Safe flights!

¡Vuele con seguridad!

ELA TEAM.